


Tack Coat Effect on Field Performance



December 2, 2014
Wisconsin Asphalt Paving Association
Madison, WI



You might have a bonding problem if ...



You definitely have a bonding problem if ...



Road Science™

Division of ArrMaz Custom Chemicals

You might have a bonding problem if ...

- Longitudinal cracking near the wheel path



Why do pavements debond?

- Lack of tack coat
- Non-uniform application of tack
- No adjustment in rate for surface type or condition
- Dirt, debris and dust contamination of surface



Why do pavements debond?

- Construction practices necessitate driving on the tack coat to place the mix
- Tracking of the tack from the surface may result



Tack Coat - Constructability vs Performance

- Traditional distributor placed tack coat construction dictates:
 - Low application rates
 - Curing of the tack
 - Traction for paving equipment
 - Use of non-tacky hard binders to reduce tracking



Tack Coat Paradigms

Heavy application of tack coat may -

- create a slip plane
- flush to the surface of the new overlay



What options are available to place tack uniformly without disturbing during construction?

- Modify the process to keep all construction equipment and trucks off the tack during construction
- Spray paver



What is a Spray Paver?



Spray Paver = Paver + Distributor in one machine




Road Science™


Division of ArrMaz Custom Chemicals

Spray Pavers

- Due to the distributor plus paver in one,
 - Different types of emulsion can be used
 - Dilution of emulsion is not required
 - Application rates are not limited by construction



ROADTEC STEALTH PAVER WITH TACK TANK



Spray Paver Experimentation (Field)

- What happens if significantly higher application rates are used?
- What forms of distress will appear or possibly be delayed?
- What effect does significantly different types of tack have on performance?
- Surface type effect on application rates (PCC, AC, milled)?



2008



2012

Field Performance Data



Route T, Franklin County, MO


- Constructed: October 2008
- Contractor: N.B. West
- Project length: 3.5 miles (test sections)
- Surface: Composite, HMA over PCC
- Mix: 1 ¾" Bonded BP-1 HMA w/ PG64-22
- Tack:
 - Test sections at 0.1, 0.15, and 0.2 gal/yd² PMAE at 65% AC
 - Test sections at 0.1 gal/yd² thru distributor and 0.1 and 0.15 gal/yd² CSS-1h thru SP-200
- Equipment: RoadTec SP-200 spray paver




June 2009

MoDOT Route T Project – Oct 2008


1 3/4" BP-1 overlay over composite pavement



MoDOT Route T 2008 @ 68 months 1 3/4" BP-1 over HMA/PCC Composite Transverse Crack Length/1000' vs Time West Bound Lane




MoDOT Route T 2008 @ 68 months 1 ¾" BP-1 over HMA/PCC Composite Longitudinal Crack Length/1000' vs Time West Bound Lane



Route T Franklin Co Test Sections 11/12 Pre-paving and 4 years later



2008



2012

0.21 gal/yd² (0.14 res) PMAE Tack




Road Science[™]
Division of ArrMaz Custom Chemicals

Route T Franklin Co Test Sections 11/12 Pre-paving and 6 years later



2008



2014

0.21 gal/yd² (0.14 res) PMAE Tack



Road Science[™]

Division of ArrMaz Custom Chemicals

KDOT US 36 Washington Co. Project – Sept 2009 1 1/2" SR-12.5A over a Milled Surface




Test Section 11 40% RAP 0.35 gal/yd ² EBL	Test Section 10 40% RAP 0.25 gal/yd ² EBL	Test Section 9 25% RAP 0.12 gal/yd ² EBL	Test Section 7 25% RAP 0.20 gal/yd ² EBL	Test Section 5 25% RAP 0.16 gal/yd ² EBL	Test Section 3 25% RAP 0.08 gal/yd ² EBL	Test Section 1 25% RAP No Tack
		Test Section 8 25% RAP 0.12 gal/yd ² CSS-1h	Test Section 6 25% RAP 0.20 gal/yd ² CSS-1h	Test Section 4 25% RAP 0.16 gal/yd ² CSS-1h	Test Section 2 25% RAP 0.08 gal/yd ² CSS-1h	

KDOT US 36 Washington Co 2009 at 43 months

1/2 Mill, 1 1/2" SR12.5A, PG58-28


Transverse Cracking/1000' section vs Time



KDOT US 36 Washington Co. at 43 months

1/2" Mill, 1 1/2" SR12.5A, PG58-28


Longitudinal Cracking/1000' section vs Time



KDOT US 36 Washington Co. at 43 months

1/2" Mill, 1 1/2" SR12.5A, PG58-28

Longitudinal Cracking/1000' section vs Time




No Tack over a Milled Asphalt Surface US 36 Washington Co. KS 2009



No tack over a milled surface – 2 years later

- US 36 Washington County, KS
- Fatigue cracking in the inside wheel path
- Effect of unbonded overlay



KDOT US 36 Washington County No Tack Section 2014



Road Science™

Division of ArrMaz Custom Chemicals

KDOT US 36 Marshall Co. (Const. 2010)

0.05
gal/yd²

undiluted
SS-1h tack
through
distributor


← Centerline joint

← Transition from
tack to polymer
modified tack
section


0.14
gal/yd²
undiluted
polymer
modified
tack
applied
through
spray paver

- 1" mill, 1" SR9.5A
- PG70-28 binder
- 5 test sections
 - 4 spray paver shot rates
 - 0.11 gal/yd² EBL
 - 0.18 gal/yd² EBL
 - 0.26 gal/yd² EBL
 - 0.36 gal/yd² EBL
 - 1 Distributor applied shot rate
 - 0.05 gal/yd² SS-1h

KDOT US 36 Marshall Co. 2010 Transverse Cracking at 43 months 1" Mill, 1" SR9.5A, PG70-28



KDOT US 36 Marshall Co. 2010 Longitudinal Cracking at 43 months 1" Mill, 1" SR9.5A, PG70-28




KDOT US 36 Nemaha County 2010


- 4" CIR with emulsion
- 1 ½" SR12.5A
- PG70-22 binder
- 4 Test sections
 - 3 spray paver shot rates
 - 0.11 gal/yd² EBL
 - 0.22 gal/yd² EBL
 - 0.34 gal/yd² EBL
 - 1 distributor applied control section
 - 0.05 gal/yd² CSS-1h



KDOT US 36 Nemaha Co. 2010 Transverse Cracking at 41 months 4" CIR w/ 1 1/2" SR12.5A, PG70-22




KDOT US 36 Nemaha Co. 2010 Longitudinal Cracking at 41 months 4" CIR w/ 1 1/2" SR12.5A, PG70-22




Saturation at Interface Creates Voidless Height in HMA

- Higher tack rate creates an asphalt rich interlayer at the interface with the existing pavement




MoDOT Route T @ 41 months Transverse Cracks vs Voidless Height




*Assumes 0.03 gsy absorption

KDOT US 36 Washington Co at 31 months Transverse Cracks vs Voidless Height All CSS-1h sections




*Assumes 0.03 gsy absorption

US 36 Marshall County, KS @ 43 months Transverse Cracks vs Voidless Height



US 36 Nemaha County, KS @ 41 Months Transverse Cracks vs Voidless Height



Observations from Field Performance

- Based on field project data,
 - Correlation of bond energy to longitudinal cracking resistance exists
 - Correlation of voidless height to transverse cracking exists
 - General trends favor higher application rates (than standard tack rates) and polymer modified tack
 - Improved mix performance; more resistance to transverse and longitudinal cracking
 - Field data from more projects are being gathered

Questions?

